SIDDALL RESIDENCE

2901 ST. JOHNS STREET, PORT MOODY CONSERVATION PLAN

NOVEMBER 2015 REVISED JULY 2016





DONALD LUXTON AND ASSOCIATES INC.

1030 - 470 GRANVILLE STEET VANCOUVER BC V6C 1V5 info@donaldluxton.com 604 688 1216 www.donaldluxton.com



TABLE OF CONTENTS

1.	INTRODUCTION	1
2.	HISTORIC CONTEXT	2
3.	STATEMENT OF SIGNIFICANCE	5
4.	CONSERVATION GUIDELINES	6
	4.1 STANDARDS AND GUIDELINES	
	4.2 CONSERVATION REFERENCES	7
	4.3 GENERAL CONSERVATION STRATEGY	8
	4.4 SUSTAINABILITY STRATEGY	
	4.5 HERITAGE EQUIVALENCIES AND EXEMPTIONS	
	4.5.1 BRITISH COLUMBIA BUILDING CODE	
	4.5.2 ENERGY EFFICIENCY ACT	
	4.5.3 HOMEOWNER PROTECTION ACT	
	4.6 SITE PROTECTION	
5.	CONDITION REVIEW AND CONSERVATION RECOMMENDATIONS	
	5.1 SITE	
	5.2 FORM, SCALE AND MASSING	
	5.3 FOUNDATION	_
	5.4 EXTERIOR WALLS	
	5.4.1 WOOD FRAME WALLS	
	5.4.2 WOOD SIDING	
	5.4.3 WOOD TRIM	
	5.5 PORCH	
	5.6 WINDOW	
	5.8 ROOF AND GUTTER	
	5.9 CHIMNEY	
	5.10 COLOUR SCHEDULE	
6.	MAINTENANCE PLAN	
٠.	6.1 MAINTENANCE GUIDELINES	
	6.2 PERMITTING	
	6.3 ROUTINE, CYCLICAL AND NON-DESTRUCTIVE CLEANING	
	6.4 REPAIRS AND REPLACEMENT OF DETERIORATED MATERIALS	
	6.5 INSPECTIONS	
	6.6 INFORMATION FILE	
	6.7 EXTERIOR MAINTENANCE	28
ΑF	PPENDIX A: EXISTING ELEVATION PHOTOS	



1.0 INTRODUCTION



HISTORIC NAME: SIDDALL RESIDENCE

CURRENT ADDRESS: 2901 ST. JOHNS STREET ORIGINAL OWNER: JAMES PRIDHAM SIDDALL

CONSTRUCTION DATE: 1922

HERITAGE STATUS: MUNICIPAL HERITAGE REGISTER; PROPOSED LEGAL PROTECTION

The Siddall Residence is a handsome example of a Craftsman bungalow, typical of the housing built during the interwar period in Port Moody. Constructed in 1922, the Siddall Residence is a one and one-half storey, rectangular-plan house that features a front-gabled roof with inset full-width front porch.

The proposed conservation strategy for the Siddall Residence involves the preservation of its exterior features and character-defining elements while relocating the historic house to nearby 123 Douglas Street. Relocating the building will ensure the conservation and retention of the structure and will situate the house among other buildings of a similar

vintage. The character-defining heritage elements to be preserved are listed in the Statement of Significance, but include: its residential form, scale and massing; simple rectangular plan; front-gabled roof with full-width front verandah; original wood construction materials; Craftsman style details; and variety of wooden sash windows.


The conservation of the house is enabled under a Heritage Revitalization Agreement with the City of Port Moody, which will include the relocation and conservation of three historic houses: the Moisio Residence; the Siddall Residence; and the Sutherland Residence.

DONALD LUXTON ASSOCIATES

2.0 HISTORIC CONTEXT

The Siddall Residence is located in Moody Centre, one of Port Moody's two Heritage Conservation Areas (HCA); the other being the loco Townsite. Encompassing the south shore of Burrard Inlet, and located adjacent to the Canadian Pacific Railway (CPR) tracks, Moody Centre was Port Moody's historic commercial and residential downtown. The main commercial area of Moody Centre includes Clarke Street and St. Johns Street, which run east-west and parallel to one another. The residential community of Moody Centre was developed immediately south of the commercial areas and extends up the Chines escarpment, a steep forested slope, which is still home to a plethora of wild flora and fauna. The character of the area is augmented by superb views to the north and by many mature landscaping elements.

Port Moody was originally surveyed by the Royal Engineers who arrived in British Columbia in 1858. The detachment was created by an Act of British Parliament and commanded by Colonel Richard Moody, after whom the area is named. Among the Royal Engineers was John Murray, who accepted the Crown's offer to sappers such as himself of 150 acres of land if they remained in British Columbia following their assignment; Murray is known today as one of Port Moody's first settlers. Following the surveying work, development in Port Moody began to increase. Settlement and construction in the area reached a new height when the CPR named Port Moody as the western terminus of the Company's cross-country line.



Port Moody, the Western Terminus of the Canadian Pacific Railway, 1884, City of Vancouver Archives (CVA) AM1594-: MAP 91

HISTORIC CONTEXT

By 1880, the area was under heavy construction in anticipation of the arrival of the railway. Infrastructure to support the impending arrival was quickly established, along with the construction of hotels, stores, offices, and houses. On July 4, 1886 the first cross-Canada train, Engine 371, arrived in Port Moody. Shortly following this momentous event however, the CPR began construction on the extension of the

rail line that would see Vancouver as the western terminus, effectively halting the rapid development of Port Moody. Development did not permanently cease however - due to its position on the CPR rail line, its location on Burrard Inlet, its variety of industries, and its proximity to Vancouver, Port Moody remained an attractive and desirable place to settle.



Arrival of train 371 to Port Moody, CVA AM54-S4-- Can P3



John Murray Property, Port Moody, 1884, CVA AM54-S4-: Out P30



Flavelle Mill, Port Moody Station Museum



loco Refinery, 1924, Acc. # 1984.104.001

Many of the houses in the vicinity of the Siddall Residence were built during the Edwardian era boom and the subsequent interwar period. A sawmill had opened in the area in 1905, employing 125 men, followed by several oil refineries. In 1915, the Imperial Oil Company established a large development just outside of the Port Moody city boundary, attracting

labourers to the area. The lumber industry continued to grow and dominate Port Moody, peaking in the 1920s, when the area was occupied by many private homes and several general stores. The Siddall Residence was among the houses constructed in Port Moody during the interwar construction boom.

STATEMENT OF SIGNIFICANCE

3.0 STATEMENT OF SIGNIFICANCE

Description of Historic Place

The Siddall Residence is a one and one-half storey Craftsman bungalow with a full basement and a frontgabled roof. The house sits on a prominent corner lot at the intersection of St. Johns and Hugh Streets.

Heritage Value

Constructed in 1922, the Siddall Residence is a well-maintained example of a bungalow that demonstrates the late persistence of the influence of the Craftsman style. The modest detailing reflects the type of residence typically built for the working class in the 1920s. The first owner, James Pridham Siddall (1883 – 1965), was employed as a saw mill engineer, and was originally from Port Phillips, Nova Scotia. In 1910, he married Helen Mae Walden (1887 – 1959), and the Siddall's lived in this house until the time of her death.

The Siddall Residence is additionally significant for its prominent location within the Moody Centre residential area, and is associated with the continuing early twentieth-century growth and economic development of Port Moody. Situated just to the east of the downtown area, it demonstrates the city's early development patterns, and the outward expansion that occurred as prosperity returned after the end of World War One.

Character-Defining Elements

Key elements that define the heritage character of the Siddall Residence include:

- corner lot location at St. Johns and Hugh Streets
- residential form, scale and massing as expressed by its one and one-half storey height, full basement, simple rectangular plan and frontgabled roof with saddlebag dormers
- construction materials such as lapped wooden siding and cedar shingles in the gable ends and at the foundation level
- Craftsman style details such as triangular eave brackets, exposed soffits, and full width open verandah with tapered columns
- internal red-brick chimney
- variety of windows including double assembly, double-hung 1-over-1 wooden sash windows, casement windows and a diamond-leaded window
- mature deciduous trees

Source: City of Port Moody Planning Department



4.0 CONSERVATION GUIDELINES

4.1 STANDARDS AND GUIDELINES

The 1922 Siddall Residence at 2901 St. Johns Street is an important heritage resource in Port Moody. The Parks Canada *Standards and Guidelines for the Conservation of Historic Places in Canada* (2010) is the source used to assess the appropriate level of conservation and intervention. Under the *Guidelines*, the work proposed for the historic house includes aspects of preservation, rehabilitation and restoration.

Preservation: the action or process of protecting, maintaining, and/or stabilizing the existing materials, form, and integrity of a historic place or of an individual component, while protecting its heritage value.

Restoration: the action or process of accurately revealing, recovering or representing the state of a historic place or of an individual component, as it appeared at a particular period in its history, while protecting its heritage value.

Rehabilitation: the action or process of making possible a continuing or compatible contemporary use of a historic place or an individual component, through repair, alterations, and/or additions, while protecting its heritage value.

Interventions to the Siddall Residence should be based upon the *Standards* outlined in the *Standards* and *Guidelines*, which are conservation principles of best practice. The following **General Standards** should be followed when carrying out any work to an historic property.

STANDARDS

Standards relating to all Conservation Projects

- Conserve the heritage value of a historic place.
 Do not remove, replace, or substantially alter its
 intact or repairable character-defining elements.
 Do not move a part of a historic place if its
 current location is a character-defining element.
- Conserve changes to a historic place, which over time, have become character-defining elements in their own right.
- 3. Conserve heritage value by adopting an approach calling for minimal intervention.
- 4. Recognize each historic place as a physical record of its time, place and use. Do not create a false sense of historical development by adding elements from other historic places or other properties or by combining features of the same property that never coexisted.
- 5. Find a use for a historic place that requires minimal or no change to its character defining elements.
- 6. Protect and, if necessary, stabilize a historic place until any subsequent intervention is undertaken. Protect and preserve archaeological resources in place. Where there is potential for disturbance of archaeological resources, take mitigation measures to limit damage and loss of information.
- 7. Evaluate the existing condition of character-defining element to determine the appropriate intervention needed. Use the gentlest means possible for any intervention. Respect heritage value when undertaking an intervention.
- Maintain character-defining elements on an ongoing basis. Repair character-defining element by reinforcing the materials using recognized conservation methods. Replace in kind any extensively deteriorated or missing parts of character-defining elements, where there are surviving prototypes.

CONSERVATION GUIDELINES

 Make any intervention needed to preserve character-defining elements physically and visually compatible with the historic place and identifiable upon close inspection. Document any intervention for future reference.

Additional Standards relating to Rehabilitation

- 10. Repair rather than replace character-defining elements. Where character-defining elements are too severely deteriorated to repair, and where sufficient physical evidence exists, replace them with new elements that match the forms, materials and detailing of sound versions of the same elements. Where there is insufficient physical evidence, make the form, material and detailing of the new elements compatible with the character of the historic place.
- 11. Conserve the heritage value and character-defining elements when creating any new additions to a historic place and any related new construction. Make the new work physically and visually compatible with, subordinate to and distinguishable from the historic place.
- 12. Create any new additions or related new construction so that the essential form and integrity of a historic place will not be impaired if the new work is removed in the future.

Additional Standards relating to Restoration

- 13. Repair rather than replace character-defining elements from the restoration period. Where character-defining elements are too severely deteriorated to repair and where sufficient physical evidence exists, replace them with new elements that match the forms, materials and detailing of sound versions of the same elements.
- 14. Replace missing features from the restoration period with new features whose forms, materials and detailing are based on sufficient physical, documentary and/or oral evidence.

4.2 CONSERVATION REFERENCES

The proposed work entails the Relocation, Restoration and Rehabilitation of the Siddall Residence.

The following conservation resources should be referred to:

Standards and Guidelines for the Conservation of Historic Places in Canada, Parks Canada, 2010. http://www.historicplaces.ca/en/pages/standards-normes/document.aspx

National Park Service, Technical Preservation Services Preservation Briefs:

Preservation Brief 4: Roofing for Historic Buildings http://www.nps.gov/tps/how-to-preserve/briefs/4-roofing.htm

Preservation Brief 9: The Repair of Historic Wooden Windows.

http://www.nps.gov/tps/how-to-preserve/briefs/9-wooden-windows.htm

Preservation Brief 10: Exterior Paint Problems on Historic Woodwork.

http://www.nps.gov/tps/how-to-preserve/briefs/10-paint-problems.htm

Preservation Brief 45: Preserving Historic Wood Porches

http://www.nps.gov/tps/how-to-preserve/briefs/45-wooden-porches.htm

Preservation Brief 47: Maintaining the Exterior of Small and Medium Size Historic Buildings.

http://www.nps.gov/tps/how-to-preserve/briefs/47-maintaining-exteriors.htm

4.3 GENERAL CONSERVATION STRATEGY

Proposed Redevelopment Scheme

The primary intent is to Relocate the Siddall Residence to 123 Douglas Street in Port Moody. It is proposed to subdivide the parcel at 123 Douglas Street into three lots. As part of the conservation work the exterior elevations of the Siddall Residence will be restored, while undertaking interior rehabilitation and upgrades to its structure and services to increase the functionality for residential use. Character-defining elements will be preserved, while missing or deteriorated elements will be restored.

An overall rehabilitation scheme has been provided by the client (refer to application drawings dated 14 July 2016). The major proposed interventions of the overall project are:

- Proposed relocation of the historic house to 123 Douglas Street in Port Moody
- Preserve exterior character-defining elements
- Restore character-defining elements that have been altered or removed

Proposed Infill Guidelines

Due to the proposed residential development on the subdivided lot, all new visible construction including new foundations and basements will be considered a modern intervention on the historic site. The *Standards and Guidelines* list recommendations for new construction related to historic places, which applies to new construction in the near vicinity of a historic structure.

The proposed design scheme for the new construction should follow **Standards 11 and 12**:

 Conserve the heritage value and characterdefining elements when creating any new additions to a historic place and any related new construction. Make the new work physically and visually compatible with, subordinate to and distinguishable from the historic place. Create any new additions or related new construction so that the essential form and integrity of a historic place will not be impaired if the new work is removed in the future.

4.4 SUSTAINABILITY STRATEGY

The four-pillar model of sustainability identifies four interlinked dimensions: environmental, economic, social and cultural sustainability, the latter including the built heritage environment. This four pillar approach was also adopted by the City of Port Moody in their Community Sustainability Plan.

Current research links sustainability considerations with the conservation of our built and natural environments. A competitive, sustainable economy requires the conservation of heritage buildings as an important component of a high quality urban environment. In a practical context, the conservation and re-use of historic and existing structures contributes to environmental sustainability by:

- Reducing solid waste disposal (reduced impact on landfills and their expansions);
- Saving embodied energy (defined as the total expenditure of energy involved in the creation of the building and its constituent materials);
- Conserving historic materials that are significantly less consumptive of energy than many new replacement materials (often local and regional materials, e.g. timber, brick, concrete, plaster, can be preserved and reduce the carbon footprint of manufacturing and transporting new materials).

The following considerations for energy efficiency in historic structures are recommended in the Parks Canada *Standards and Guidelines for the Conservation of Historic Places in Canada* (2010) and can be utilized for the Siddall Residence.

CONSERVATION GUIDELINES

Sustainability Considerations

- Add new features to meet sustainability requirements in a manner that respects the exterior form and minimizes impact on character-defining elements.
- Comply with energy efficiency objectives in a manner that minimizes impact on the characterdefining elements and overall heritage value of the historic building.



Four Pillar Approach, City of Port Moody

4.5 HERITAGE EQUIVALENCIES & EXEMPTIONS

Through the Heritage Revitalization Agreement the 1922 Siddall Residence will become legally protected. It will be eligible for heritage variances that will enable a higher degree of heritage conservation and retention of original material, including considerations available under the following municipal legislation.

4.5.1 BRITISH COLUMBIA BUILDING CODE

Building Code upgrading ensures life safety and longterm protection for historic resources. It is important to consider heritage buildings on a case-by-case basis, as the blanket application of Code requirements do not recognize the individual requirements and inherent strengths of each building.

Over the past few years, a number of equivalencies have been developed and adopted in the British Columbia Building Code (2012) that enable more sensitive and appropriate heritage building upgrades.

For example, the use of sprinklers in a heritage structure helps to satisfy fire separation and exiting requirements. Table A-1.1.1.1., found in Appendix A of the Code, outlines the "Alternative Compliance Methods for Heritage Buildings."

Given that Code compliance is such a significant factor in the conservation of heritage buildings, the most important consideration is to provide viable economic methods of achieving building upgrades. In addition to the equivalencies offered under the current Code, the City of Port Moody can also accept the report of a Building Code Engineer as to acceptable levels of code performance.

If fire separation needs to be upgraded between the heritage house and the infill buildings, sprinklers or intumescent paint are recommended. The installation of fibre-cementitious siding, such as Hardie Board, is not a recommended intervention on the heritage building.

4.5.2 ENERGY EFFICIENCY ACT

The provincial *Energy Efficiency Act* (Energy Efficiency Standards Regulation) was amended in 2009 to exempt buildings protected through heritage designation or listed on a community heritage register from compliance with the regulations. Energy Efficiency standards therefore do not apply to windows, glazing products, door slabs or products installed in heritage buildings. This means that exemptions can be allowed to energy upgrading measures that would destroy heritage character-defining elements such as original windows and doors. These provisions do not preclude that heritage buildings must be made more energy efficient, but they do allow a more sensitive approach of alternate compliance to individual situations and a higher degree of retained integrity. Increased energy performance can be provided through non-intrusive methods of alternate compliance, such as improved insulation and mechanical systems. Please refer to the Standards and Guidelines for the Conservation of Historic Places in Canada (2010) for further detail about "Energy Efficiency Considerations."

DONALD LUXTON ASSOCIATES

4.5.3 HOME OWNER PROTECTION ACT

Amendments to the Homeowner Protection Act Regulation made in 2010 allow for exemptions for heritage sites from the need to fully conform to the BC Building Code under certain conditions, thus removing some of the barriers to compliance that previously conflicted with heritage conservation standards and guidelines. The changes comprised

- (1) an amendment to the Homeowner Protection Act Regulation, BC Reg. 29/99 that allows a warranty provider, in the case of a commercial to residential conversion, to exclude components of the building that have heritage value from the requirement for a warranty, and
- (2) clarification of the definition of 'substantial reconstruction.' The latter clarification explains that 75% of a home must be reconstructed for it to be considered a 'new home' under the Homeowner Protection Act, thus enabling single-family dwelling to multi-family and strata conversions without the Act coming into play. The definition of a heritage building is consistent with that under the Energy Efficiency Act.

4.6 SITE PROTECTION

It is the responsibility of the owner to ensure the heritage resource is protected from damage at all times. At any time that the house is left vacant and/or relocated and lifted, it should be secured against unauthorized access or damage through the use of appropriate fencing and security measures. A site protection plan may be developed in discussion between owner, contractor and/or architect based on the following checklist:

Moisture

- Is the roof watertight?
- Are openings protected?
- Is exterior cladding in good condition to keep water out?

Ventilation

- Have steps been taken to ensure proper ventilation of the building?
- Have interior doors been left open for ventilation purposes?
- Has the secured building been checked within the last 3 months for interior dampness or excessive humidity?

Pests

- Have nests/pests been removed from the building's interior and eaves?
- Are adequate screens in place to guard against pests?
- Has the building been inspected and treated for termites, carpenter ants, rodents, etc.?

Security

- Are smoke and fire detectors in working order?
- Are wall openings boarded up and exterior doors securely fastened?
- Are plans in place to monitor the building on a regular basis?
- Are the keys to the building in a secure but accessible location?
- Are the grounds being kept from becoming overgrown?

In addition to the above recommendations, a sign should be installed at the site to inform the public that this house is a historic resource and will be conserved. A contact number should be provided for concerned citizens who observe trespassing or other unauthorized activities at the site.

CONSERVATION GUIDELINES



5.0 CONDITION REVIEW & CONSERVATION RECOMMENDATIONS

During a site visit the condition of the exterior materials of the Siddall Residence at 2901 St. Johns Street was reviewed. In addition to the visual review of the elevations, paint samples were removed from original materials for colour analysis. The recommendations for the preservation and restoration of the 1922 Siddall Residence are based on the site review and material assessments that provide valuable information about the historic appearance of the house.

The house is presently not occupied, but was continuously used as a residential building. Recommendations for protecting the historic site, in particular during times of vacancy, are outlined in 4.6 Site Protection. The following chapter describes the materials, physical condition and recommended conservation strategy for the historic structure based on Parks Canada's *Standard and Guidelines for the Conservation of Historic Places in Canada* (2010).

5.1 SITE

The Siddall Residence is prominently situated at the corner of St. Johns Street and Hugh Street in the Moody Centre neighbourhood. The large corner lot borders St. Andrews Street at the south, which is also where a later garage is located. The lot slopes towards the south and has some mature vegetation.

As part of the redevelopment scheme it is proposed to relocate the Siddall Residence to 123 Douglas Street in Moody Centre. Two additional historic houses will also be relocated to this property (Moisio Residence, presently 2101 Clarke Street, and Sutherland Residence, 2830 St. George Street).

Design guidelines for new construction are listed in 4.3 General Conservation Strategy. They aim to preserve the heritage value and character-defining elements of the Siddall Residence and to make the new work compatible with the historic building. The proposed relocation of the Siddall Residence within Moody Centre ensure the ongoing conservation of the historic structure while retaining its overall neighbourhood context.

Conservation Strategy: Rehabilitation

The following **Relocation Guidelines** should be implemented:

- A relocation plan should be prepared prior to relocation that ensures that the least destructive method of relocation will be used.
- Alterations to the historic structure to facilitate the relocation process should be evaluated in accordance with the Conservation Plan. The building should be structurally braced as required. This is the responsibility of the professional building relocation company.
- Only an experienced and qualified contractor shall undertake the physical relocation of the historic structure.
- Appropriate foundation materials can be used at the new site, which can include reinforced concrete basement walls and slab.
- Provide utility installations for electricity, communication and other service connections underground. All installations located above ground should be incorporated harmoniously into the design concept for the relocated structure.
- Implement measures for site protection, in particular when the house sits vacant, and until construction work commences.

5.2 FORM, SCALE AND MASSING

The 1922 Siddall Residence features a residential form, scale and massing as expressed by its onestorey full height, full basement, simple rectangular plan, front-gabled roof and dormers.

Conservation Strategy: Preservation


 Preserve the overall form, scale and massing of the Siddall Residence.

5.3 FOUNDATION

The historic house has a full basement consisting of poured-in-place concrete foundation walls and concrete slab. The proposed relocation of the house requires lifting the structure at the main floor and placing it onto new concrete foundations. The existing concrete foundation will be demolished.

Conservation Strategy: Rehabilitation

- The house will be relocated and placed onto new reinforced concrete foundation.
- New door and window openings at the basement level can be designed. They should be sympathetic to the historic character of the house and made of wood.
- To ensure the prolonged preservation of the new foundations, all landscaping should be separated from the foundations at grade by a course of gravel or decorative stones, which help prevent splash back and assist drainage.









- Ocurrent Address: 2901 St. Johns St.
- Future Address: 123 Douglas St.



5.4 EXTERIOR WALLS

5.4.1 WOOD FRAME WALLS

Dimensional lumber is the traditional building material used for the house. Wood-frame construction is one of the most affordable housing construction methods that utilized in the past old growth lumber. The installation of new insulation can be done from the inside while preserving architectural elements.

Conservation Strategy: Preservation

- Preserve the existing wood-frame structure of the original house.
- Design structural and seismic upgrades, if required, from the inside without impacting exterior character-defining elements.
- Utilize Alternate Compliance Methods outlined in the applicable building code for fire and spatial separations including installation of sprinklers where required.

5.4.2 WOOD SIDING

The original wood lap siding and cornerboards on the main floor is still in place and in good condition except for peeling paint.

At the basement level and the elevations above the second floor joists are finished with cedar shingles, which show some signs of weathering. The lap and shingle siding are important architectural elements of the house and should be preserved and restored. Severely damaged siding can be replaced with appropriate replica siding matching the original profile. The basement will be rehabilitated and new cedar shingles matching the original should be installed.

Conservation Strategy: Restoration


 Retain lap and shingle siding and cornerboards, and restore in-place. Replace any damaged lap siding to match existing in material, size, profile.

- Combed or textured lumber, vinyl or fibre cement siding are not acceptable replacement materials on the historic house.
- Cleaning procedures of lap siding should be undertaken with non-destructive methods.
 Areas can be cleaned using a soft, natural bristle brush, without water, to remove dirt and other material. If a more intense cleaning is required, this can be accomplished with warm water, mild detergent (such as Simple Green) and a soft bristle brush. High-pressure power washing, abrasive cleaning or sandblasting should not be allowed under any circumstances on any historic material of the exterior elevations.
- Install new cedar shingles at the basement level matching the originals in overall dimensions and installation pattern.

5.4.3 WOOD TRIM

Original wood trim is visible on the elevations including wide window and door trim with crown mouldings, watertable, and bargeboards, which should be preserved and repaired in-situ. Damaged or deteriorated trim should be replaced in kind.

- Retain original trim that is in good or repairable condition.
- Cut out deteriorated trim sections and install matching trim board that is visually and physically compatible with the original.
- Combed or textured lumber, vinyl or fibre cement siding are not acceptable replacement materials on the historic house.





Clockwise from Top: Shingle siding at second floor; Lap siding, belt course, watertable and cornerboard; Shingle siding at basement; Door trim



5.5 PORCH

The Siddall Residence has an original full-length front porch with three tapered columns, open balustrade and tongue-and-groove flooring and soffit. Some signs of water damage and deterioration, particularly rot at the bottom of the columns, is visible.

The original wooden stair with nine treads and closed risers, starting and end newels, and handrails with banisters is still extant but is also weathered. It appears though that the treads were replaced in the past. The stair may not be salvageable due to the relocation of the house.

A smaller rear porch on the south elevation with a later wooden stair exists adjacent to a one-storey extension, all covered with a shed roof. The rear porch can be removed if desired.

Conservation Strategy: Restoration/Rehabilitation

- Preserve and restore the front porch including the timber columns, balustrade, soffit, mouldings and other features as a significant characterdefining element.
- In order to meet building code requirements some rehabilitation measures may be required; e.g. floors above occupied spaces will require a waterproof membrane with new wooden decking over top. The design of the porch deck should be reviewed to ensure that the final appearance does not conflict with the restoration intent.
- Alternate compliance method will allow to retain the original balustrades while meeting building code requirements, e.g. installing glass panels or metal railings.
- Build a new wooden front stair that matches the original stair in design and location.









Clockwise from top left: Tongue and groove flooring; Tongue and groove flooring and closed riser; Front porch; Stairs with starting and end newels, and handrails with banisters









Top Left: Tongue and groove soffit and flooring; Bottom left: Tapered column; Top right and bottom right: Rear porch



5.6 WINDOW

Windows and doors are among the most conspicuous feature of any building. In addition to their function — providing light, views, fresh air and access to the building — their arrangement and design is fundamental to the building's appearance and heritage value. Each element of fenestration is, in itself, a complex assembly whose function and operation must be considered as part of its conservation. — Standards and Guidelines for the Conservation of Historic Places in Canada (2010).

The original window assemblies of the Siddall Residence comprise mostly of pairs of original one-over-one, double hung wooden sash windows on all elevations. They show the typical sash horns, a historic detail of these window types. Other window configurations include a piano window with leaded and stained glass on the west elevation, and pairs of casement windows on the east and south elevations. The dormer on the east side features a pair of hopper windows. The original wood windows should be preserved and restored.

- Retain the original wood sash windows in their original openings.
- Restore deteriorated or damaged wood elements where possible (e.g. sashes, sills), and replace elements that are missing or too deteriorated to be repaired.
- Overhaul, tighten/reinforce joints of original windows. Repair frame, trim and hardware.
 Each original window should be made weather tight by re-puttying and weather-stripping as necessary.
- Retain historic glass of original windows including leaded glass.
- Window restoration should be undertaken by a contractor skilled in heritage restoration.
- Replicate missing window to match original in material, dimensions and detailing including the typical arched header.
- The consultant can review window shop drawings and mock-ups for new windows.
- Prime and paint all wood windows as required in appropriate colours, based on colour schedule devised by the Heritage Consultant.



Pair of original one-over-one, double hung wooden sash windows on second storey of front façade





Window assemblies on the east and south (rear) elevations













Window assemblies on the west elevation











Piano window with leaded and stained glass



5.7 DOOR

The house has two original doors on the front and rear elevations. The doors are similar in their design with multi-panelling in the lower section and glazing above. These doors should be retained if possible. On the east elevation a later basement door exists, which will be removed as part of the proposed relocation of the house.

- Preserve the original door opening, front and surrounding trim. Retain the rear door if possible.
- To improve operation, verify that door fits properly in its frame and joints are tight. Verify that hardware is operational, particularly that hinges are tight and hinge pins not worn.
 Remove built-up paint at door and jamb. Repair damaged elements to match original. To reduce air infiltration, install weather stripping between door and frame.
- New doors should be sympathetic to the historic character of the house and made of wood.



Front door



Rear door

5.8 ROOF AND GUTTER

The Siddall Residence preserved the original roof design with a front-gabled roof and shed dormers on either side. A smaller rear porch and one-storey extension are covered with a shed roof as well. The original cedar roof shingles were replaced over time with asphalt shingles. The house features also open eaves with exposed rafter tails and triangular eave brackets at the front and rear gables. The gutters and downspouts are disconnected or damaged in some locations and should be replaced.

Conservation Strategy: Restoration / Rehabilitation


- Preserve and repair the original roof design of the Siddall Residence.
- The roof should be re-shingled with cedar shingles. An alternate material is 'Enviroshingle Silvered Cedar' by Enviroshake or approved equivalent. Asphalt shingles may be acceptable in dark grey or black colour after a review the by Heritage Consultant.
- Design an adequate rainwater disposal system and ensure drainage from the elevations.

5.9 CHIMNEY

An original internal chimney built with common red brick exists. A concrete cap and metal flashings were installed later. When viewed from the ground the brick chimney shows signs of weathering including significant organic growth, deteriorated mortar, failing flashings etc. Further assessments of the condition of the brickwork should be carried out when access is available. The brick chimney is a character-defining element and should be relocated with the house.

- The existing brick chimney should be retained in place and relocated with the house, if possible.
- The brickwork can be gently cleaned of dirt and the brickwork re-pointed as necessary with suitable mortar. The brickwork will remain unpainted.
- If the condition of the brick chimney is too deteriorated to be repaired, it should be carefully dismantled and bricks salvaged and used as examples for replacement bricks. A new chimney should be built to match the original in dimensions, material, and colour.
- New metal flashings should be installed.







Chimney



Triangular eave bracket

5.10 COLOUR SCHEDULE

An important part of the restoration process of the Siddall Residence is to finish the building in historically accurate paint colours. The colour scheme is taken from Benjamin Moore's *Historical True Colours for Western Canada*, which is based on paint chips removed from the exterior elevations of the house and documented historic paint colours from this time period.

- Reinstate a historically appropriate colour scheme for the Siddall Residence, complete with historically appropriate finishes, hues and placement of applied colour. Complete all basic repairs and replacements and remove surface dust and grime before preparing, priming and painting. Be sure that all surfaces to be painted are dry. Scrape and sand painted surfaces only as deep as necessary to reach a sound base. Do not strip all previous paint except to repair basematerial decay.
- Paint all areas of exposed wood elements with paint primer. Select an appropriate primer for materials being painted (e.g. if latex paint is used over original oil paint, use an oil-based primer).
- Any substitutions or matching of custom colours shall be reviewed by the consultant. Test samples should be applied to the building prior to the commencement of painting so that the colour scheme can be reviewed under field conditions and approved.

COLOUR SCHEME Siddall Residence, 2901 St. Johns Street, Port Moody

Benjamin Moore's Historical True Colours

ELEMENT	COLOUR & CODE	SAMPLE
Siding	Oxford Ivory VC-1	
Cornerboard, Watertable	Oxford Ivory VC-1	
Porch column, balustrade sill, balustrade pickets	Oxford Ivory VC-1	
Window trim	Oxford Ivory VC-1	
Window sash	Gloss Black VC-35	
Door trim	Oxford Ivory VC-1	
Front door	Medium-Dark Stain & Varnish	
Basement shingles	Strathcona Mahogany VC-34	
Basement window trim	Oxford Ivory VC-1	
Basement window sash	Gloss Black VC-35	
Gable Shingles	Vancouver Green VC-20	

6.0 MAINTENANCE PLAN

A Maintenance Plan should be adopted by the property owner, who is responsible for the long-term protection of the heritage features of the historic building. The Maintenance Plan should include provisions for:

- Copies of the Maintenance Plan and Conservation Plan to be incorporated into the terms of reference for the management and maintenance contract for the building;
- Cyclical maintenance procedures to be adopted as outlined below;
- Record drawings and photos of the building to be kept by the management / maintenance contractor; and
- Records of all maintenance procedures to be kept by the owner.

A thorough Maintenance Plan will ensure the integrity of the Siddall Residence is preserved. If existing materials are regularly maintained and deterioration is significantly reduced or prevented, the integrity of materials and workmanship of the structure will be protected. Proper maintenance is the most cost effective method of extending the life of a building, and preserving its character-defining elements. The survival of historic buildings in good condition is primarily due to regular upkeep and the preservation of historic materials.

6.1 MAINTENANCE GUIDELINES

A maintenance schedule should be formulated that adheres to the *Standards and Guidelines for the Conservation of Historic Places in Canada* (2010). As defined by the *Standards and Guidelines*, maintenance is defined as:

Routine, cyclical, non-destructive actions necessary to slow the deterioration of a historic place. It entails periodic inspection; routine, cyclical, non-destructive cleaning; minor repair and refinishing operations; replacement of damaged or deteriorated materials that are impractical to save.

The assumption that newly renovated buildings become immune to deterioration and require less maintenance is a falsehood. Rather, newly renovated buildings require heightened vigilance to spot errors in construction where previous problems had not occurred, and where deterioration may gain a foothold.

Routine maintenance keeps water out of the building, which is the single most damaging element to a heritage building. Maintenance also prevents damage by sun, wind, snow, frost and all weather; prevents damage by insects and vermin; and aids in protecting all parts of the building against deterioration. The effort and expense expended on an aggressive maintenance will not only lead to a higher degree of preservation, but also over time potentially save large amount of money otherwise required for later repairs.

6.2 PERMITTING

Once the project is completed, any repair activities, such as simple in-kind repair of materials, should be exempt from requiring municipal permits. Other more intensive activities will require the issuance of a Heritage Alteration Permit.

6.3 ROUTINE CYCLICAL AND NON-DESTRUCTIVE CLEANING

Following the Standards and Guidelines for the Conservation of Historic Places in Canada, be mindful of the principle that recommends "using the gentlest means possible." Any cleaning procedures should be undertaken on a routine basis and should use non-destructive methods. Exterior elements are usually easily cleaned, simply with a soft, natural bristle brush, without water, to remove dirt and other material. If a more intensive cleaning is required, this can be accomplished with warm water, mild detergent and a soft bristle brush. High-pressure washing, sandblasting or other abrasive cleaning should not be undertaken under any circumstances.

6.4 REPAIRS AND REPLACEMENT OF DETERIORATED MATERIALS

Interventions such as repairs and replacements must conform to the *Standards and Guidelines* for the Conservation of Historic Places in Canada. The building's character-defining elements – characteristics of the building that contribute to its heritage value (and identified in the Statement of Significance) such as materials, form, configuration, etc. - must be conserved, referencing the following principles to guide interventions:

- An approach of minimal intervention must be adopted - where intervention is carried out it will be by the least intrusive & gentlest means possible.
- Repair rather than replace character-defining elements.
- Repair character-defining elements using recognized conservation methods.
- Replace 'in kind' extensively deteriorated or missing parts of character-defining elements.
- Make interventions physically and visually compatible with the historic place.

6.5 INSPECTIONS

Inspections are a key element in the maintenance plan, and should be carried out by a qualified person or firm, preferably with experience in the assessment of heritage buildings. These inspections should be conducted on a regular and timely schedule. The inspection should address all aspects of the building including exterior, interior and site conditions. It makes good sense to inspect a building in wet weather, as well as in dry, in order to see how water runs off – or through – a building.

From this inspection, an inspection report should be compiled that will include notes, sketches and observations. It is helpful for the inspector to have copies of the building's elevation drawings on which to mark areas of concern such as cracks, staining and rot. These observations can then be included in the report. The report need not be overly complicated or formal, but must be thorough, clear and concise. Issues of concern, taken from the report should then be entered in a log book so that corrective action can be documented and tracked.

An appropriate schedule for regular, periodic inspections would be twice a year, preferably during spring and fall. The spring inspection should be more rigorous since in spring moisture-related deterioration is most visible, and because needed work, such as painting, can be completed during the good weather in summer. The fall inspection should focus on seasonal issues such as weather-sealants, mechanical (heating) systems and drainage issues. Comprehensive inspections should occur at five-year periods, comparing records from previous inspections and the original work, particularly in monitoring structural movement and durability of utilities. Inspections should also occur after major storms.

6.6 INFORMATION FILE

The building should have its own information file where an inspection report can be filed. This file should also contain a log book that itemizes problems and corrective action. Additionally, this file should contain building plans, building permits, heritage reports, photographs and other relevant documentation so that a complete understanding of the building and its evolution is readily available, which will aid in determining appropriate interventions when needed.

The file should also contain a list outlining the finishes and materials used, and information detailing where they are available (store, supplier). The building owner should keep on hand a stock of spare materials for minor repairs.

LOG BOOK

The maintenance log book is an important maintenance tool that should be kept to record all maintenance activities, recurring problems and building observations and will assist in the overall maintenance planning of the building.

Routine maintenance work should be noted in the maintenance log to keep track of past and plan future activities. All items noted on the maintenance log should indicate the date, problem, type of repair, location and all other observations and information pertaining to each specific maintenance activity. Each log should include the full list of recommended maintenance and inspection areas noted in this Maintenance Plan, to ensure a record of all activities is maintained. A full record of these activities will help in planning future repairs and provide valuable building information for all parties involved in the overall maintenance and operation of the building, and will provide essential information for long term programming and determining of future budgets. It will also serve as a reminded to amend the maintenance and inspection activities should new issues be discovered or previous recommendations prove inaccurate.

The log book will also indicate unexpectedly repeated repairs, which may help in solving more serious problems that may arise in the historic building. The log book is a living document that will require constant adding to, and should be kept in the information file along with other documentation noted in section 6.6 Information File.

6.7 EXTERIOR MAINTENANCE

Water, in all its forms and sources (rain, snow, frost, rising ground water, leaking pipes, back-splash, etc.) is the single most damaging element to historic buildings. The most common place for water to enter a building is through the roof. Keeping roofs repaired or renewed is the most cost-effective maintenance option. Evidence of a small interior leak should be viewed as a warning for a much larger and worrisome water damage problem elsewhere and should be fixed immediately.

6.7.1 INSPECTION CHECKLIST

The following checklist considers a wide range of potential problems specific to the historic building such as water/moisture penetration, material deterioration and structural deterioration.

EXTERIOR INSPECTION

Site	e Inspection Is the lot well drained? Is there pooling of water? Does water drain away from foundation?
Fo:	Indation Moisture: Is rising damp present? Is there back splashing from ground to structure? Is any moisture problem general or local? Is uneven foundation settlement evident? Do foundation openings (doors and windows
	show: rust; rot; insect attack; paint failure; soil build-up?
Ma □	Are moisture problems present? (Rising damp, rain penetration, condensation, water run-off from roof, sills, or ledges?)
	Are there cracks due to shrinking and expansion?
	Are there cracks due to structural movement? Are there unexplained cracks? Do cracks require continued monitoring? Is stucco well adhered or bulging? Location? Are there signs of steel or iron corrosion? Does the surface need cleaning?
Co	ndition of Exterior Painted Materials
	Paint shows: blistering, sagging or wrinkling, alligatoring, peeling. Cause?
	Paint has the following stains: rust, bleeding knots, mildew, etc. Cause?
	Paint cleanliness, especially at air vents?

6.7.2 INSPECTION CYCLE

Win	Is there glass cracked or missing? If the glazing is puttied has it gone brittle and cracked? Fallen out? Painted to shed water? If the glass is secured by beading, are the beads in good condition? Is there condensation or water damage to the paint? Are the sashes easy to operate? If hinged, do they swing freely? Is the frame free from distortion? Do sills show weathering or deterioration?	 Daily Observations noted during cleaning (cracks; damp, dripping pipes; malfunctioning hardware; etc.) to be noted in log book or building file. Semi-annually Semi-annual inspection and report with special focus on seasonal issues. Thorough cleaning of drainage system to cope with winter rains and summer storms Check condition of weather sealants (Fall). Clean the exterior using a soft bristle broom/
Do	ors	brush.
	Do the doors create a good seal when closed? Are the hinges sprung? In need of lubrication? Do locks and latches work freely? Is the glass in good condition? Does the putty need repair? Are door frames wicking up water? Where? Why? Are door frames caulked at the cladding? Is the caulking in good condition? What is the condition of the sill?	 Annually (Spring) Inspect foundation for cracks, deterioration. Inspect metal elements, especially in areas that may trap water. Inspect windows for paint and glazing compound failure, corrosion and wood decay and proper operation. Complete annual inspection and report. Clean out of all perimeter drains and rainwater systems. Touch up worn paint on the building's exterior. Routine cleaning, as required.
	Are downspouts leaking? Clogged? Are there	Five-Year Cycle
	holes or corrosion? (Water against structure) Are downspouts complete without any missing sections? Are they properly connected? Is the water being effectively carried away from	 A full inspection report should be undertaken every five years comparing records from previous inspections and the original work, particularly
	the downspout by a drainage system? Do downspouts drain completely away?	monitoring structural movement and durability of utilities.Repaint wood windows every five to fifteen years
Roc	of	Repairt wood windows every live to litteen years
	Are there water blockage points? Are flashings well seated? Are metal joints and seams sound? If there is a lightening protection system are the cables properly connected and grounded? Is there rubbish buildup on the roof? Are there blisters or slits in the membrane? Are the drain pipes plugged or standing proud? Are flashings well positioned and sealed? Is water ponding present?	 Ten-Year Cycle Check condition of roof every ten years after last replacement. Twenty-Year Cycle Confirm condition of roof and estimate effective lifespan. Replace when required. Major Maintenance Work (as required) Replacement of deteriorated building materials as required.





North elevation (St. Johns Street façade), October 2015



South elevation, October 2015



East elevation, October 2015



West elevation, October 2015